



REMINGTON ARMS COMPANY, INC.

SPORTING FIREARMS, AMMUNITION, TARGETS AND TRAPS
ILION, NEW YORK 13357

PAGE 1
02/13/91
DATE:

PARTS: (315) 895-7493, REPAIRS: (315) 895-7791

SOLD TO
REPAIR ORDER NO.: 9033774

SHIPPED TO
REPAIR ORDER NO. 1033774

HEDGECOTH, BILLY JOE
ROUTE 2 BOX 45
DEKALB MS 39328

HEDGECOTH, BILLY JOE
ROUTE 2 BOX 45
DEKALB MS 39328

THIS IS A DESCRIPTION OF OUR CHARGES FOR THE REPAIR OR RECONDITIONING OF THE ITEM(S) DESCRIBED BELOW. SHIPMENT WILL BE MADE IN APPROXIMATELY 4 WEEKS.

700 0000222 BUL SERIAL NUMBER: B6358731
W/STUDS L/SIGHTS

CUSTOMER REQUEST:
GUN FIRES WITHOUT TOUCHING TRIGGER

MAIN FAULT FOUND:
TRIGGER ASSEMBLY IS CONTAMINATED WITH STICKY - GUMMY RESIDUE
INTERNAL TRIGGER PARTS ARE NOT MOVING FREELY - SEAR - SAFETY
CAM IS STICKING TO TRIGGER ASSEMBLY SIDE PLATES - STICKY RESIDUE
ON BOTTOM OF RECEIVER ALSO - THIS RIFLE HAS NOT BEEN PROPERLY
MAINTAINED - TRIGGER PULL 4 3/4 POUNDS SEAR LIFT .011

- 1 0026045 TRIGGER ASSEM RM
- 1 0040982 MAG FOLLOWER
- 1 0033450 BUL ASSEM 22/250
- 1 0023711 BUL BOLT ASSEM 300-243-0MM
- 1 0016715 MAGAZINE 244 REM
SPECIAL PRICE
GO AHEAD PER PHONE 2-11-91
KOSSEL

155.95

TOTAL REPAIR CHARGE 155.95
TAXES 9.36

INSURANCE
PARCEL POST 5.00

TOTAL CHARGES 170.31

ALL PRICES QUOTED ARE IN DOLLARS FOR REPAIRED PARTS

FEB 21 1991

804923 REV 2, 90