

BARBER - Kinzer PPS GAL RE0002286 ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/20/90	DATE OPENED 12/27/90	DATE CODE BC 1-82	SERIAL NUMBER B6358731	MODEL AND GRADE 700 222 BDL		ORDER R 90-337	
ACCESSORIES W/STUDS		L/SIGHTS					

FROM:	SHIP TO:
HEDGPETH, BILLY JOE ROUTE 2 BOX 45 DEKALB MS 39328	HEDGPETH, BILLY JOE ROUTE 2 BOX 45 DEKALB MS 39328

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 1-10-91	VIA V408B644
----------------	--------------------	--------------------------------	------------	------------	----------------------	-----------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST: *Gun fires without Touching Trigger*

MAIN FAULT: *Trigger assembly is contaminated with sticky, gunpowder residue - internal trigger parts are not moving freely, rear sight can't stick to trigger assembly side plates. Sticky residue on bottom of receiver also. This rifle has not been properly maintained. Trigger pull 4 3/4 pounds, rear-sight .011"*

PARTS: *offer to clean present trigger assembly (if possible) or, we can install a new trigger assembly at 1/2 normal cost, as a gesture of good-will, if this will better restore confidence in the rifle.*

REPAIRMAN WBS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90