

P.I. YES EQUIPMENT IDENTIFICATION NUMBER: 62 MODEL: 700
 GENERAL CONDITION: USED R #: 02321
 OUTSIDE WORK: SIGHTS AND STOCK MISSING DATE: 1-15-79
SCOPE BASE ADDED FROM: VEIL-L. HEBGLAND
BOX 1744
 FIRED AMMO TYPE: UNKNOWN STEAMBOAT SPY, COLORADO
 & CONDITION: _____ GUN #: 6359039
 PROOF: (REP) A INSP.: 58 TEST: 87 CODE: XT = 12-70
 HEADING: _____ GA./CAL.: 264 WIN. MAG
 BREECH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: RDH 2/16/79
 CHAMBER: OK APPROVED: RDH 2/16/79
 TEST: OK APPROVED: RDH 2-16-79
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: RDH 2-16-79
BRIGHT METAL SHOWING ON BBL AND ZELE
AND FLOOR PLATE.

COMPLAINT: WEAPON DISCHARGED WHEN SAFETY
WAS JOSHED TO OFF SAFE POSITION

INCIDENT: SHOOT HOLE IN BACK OF PICKUP TRUCK
CAB, A VEST AND PICK UP BOX.

COMMENTS: Malfunction appears to have been caused by
excessive oil in trigger mechanism. RDH confirmed
malfunction at low temperature test (0°F).

Trigger has been adjusted outside Remington
as evidenced by block lacquer on adjusting screws.
Engagement .050.