

TLW0300Y

M/710 241095 Remington 30064 Ammo
 10 Round Test 11-17-00 Jeff W.

B1 10 rounds ✓ No problems

B2 10 " ✓ " "

B3 10 " ✓ " "

B4 10 " ✓ " "

B5 10 " ✓ " "

B6 10 " ✓ " "

B7 10 " ✓ " "

~~B8~~

B9 10 " ✓ " "

B10 10 " ✓ " "

11-20-00

B11 10 rounds ✓ No Problems

B12 10 " ✓ " " Bolt hard to close

B13 10 " ✓ " "

B14 10 " ✓ " " Grip cap came off
after 3 rounds

B15 10 " ✓ " "

B16 10 " ✓ " " Grip cap came off
after 5 rounds

B17 10 " ✓ " "

B18 10 " ✓ " " Grip cap came off
after 6 rounds

B19 10 " ✓ " "

B20 10 " ✓ " "

11-21-00

83

ET07595

M/710 241095 Remington 30064 Ammo
10 Round Test 11-15-00 Jeff W.
B21 10 rds. ✓ No Problems
B22 10 rds. ✓ " "
B23 10 rds. ✓ " "
B24 10 rds. ✓ " "
B25 10 rds. ✓ " "
B26 10 rds. ✓ " "
B27 10 rds. ✓ " "
B28 10 rds. ✓ " "
B29 10 rds. ✓ " "
B30 10 rds. ✓ " "

83

ET07596