

Jan 7th 1982

Remington Arms Co. Inc.
Arms Service Dept.
Ilion, N.Y. 13357

Att: Mr. El

For our phone conversation on 1-7-82
I am returning 7041 Model 700 B.D. 30.06
for you to replace. The gun will
discharge when the safety is moved
to the fire position. This has happened
twice. The last time removed part of
the dark end front of my motor home.

Please see other instructions I am sending
the gun for collect.

Thank you for your help

Dr. Alexander
6430 Newbort Dr.
College Park, Georgia 30537

Record - 100 1956
Serial No. - 46 934-714
140000000 271301
Serial No. - 5792