

M/700 Customer Complaint
MODEL: 700 BDL
R #: 015571
DATE: 8-14-72
FROM: HIGHSPIRE SPTG. GOODS INC.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____GENERAL CONDITION: NEWOUTSIDE WORK: NOFIRED AMMO TYPE: FACTORY LOADS

& CONDITION: _____

PROOF: R.E.P.-E INSP.: 74 TEST: 49HEADING: MAX. WITH ASSEMBLY MAX.BREECH OPENING: -RECOIL SHOULDERS: EXCESSIVE RADIUS BACK OF LUGS.CHAMBER: O.K.TEST: NO

COMPONENT CONDITION: (Damaged, Broken, Old Style)

HIGHSPIRE, PA.GUN #: 6312165CODE: LT= 2/70GA./CAL.: 3006CHECKED BY: C. PROSSER

APPROVED: _____

APPROVED: _____

APPROVED: _____

APPROVED: _____

SEAR-TRIGGER CONNECTOR ENGAGEMENT .010 (MIN. IS .020)BURRS ON SIDES OF UPPER PART OF TRIGGER SHOW FRICTIONMARKS, POOR COLOR ON BARREL AT REAR SIGHT.COMPLAINT: "FIRES JUST AS BOLT IS CLOSED."INCIDENT: FOLLOW DOWNCOMMENTS: THE TRIGGER BIND WITH UNDER MIN. ENGAGEMENT
CAUSED ERRATIC TRIGGER RETRACTION AND FOLLOW
DOWN.