

BARBER - Kinzer PPS GAL RE0002348

RECEIVING AND ESTIMATING REPORT

to Product Service

ORDER
R93-25212

INITIAL	CUSTOMER ORDER NO.				
FPS					
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/16/93	11/19/93	DP 9-67	96645		600 243 WIN
ACCESSORIES W/STUDS W/SWIVELS					

FROM: <i>[Signature]</i>	SHIP TO:
HITCHIN POST SPORTS 124 N MONTANA DILLON MT 59725	HITCHIN POST SPORTS 124 N MONTANA DILLON MT 59725

L CUST NO:003292 C.O.D L	
ACCOUNT NUMBER	ACCOUNT NUMBER W/C
WRITE ☐	PROM. DATE ESTIMATED VIA UPS
GUN CONDITION	REPAIR CHARGE <i>20.</i>
☐ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT *Mfg 1967, upon receipt, could not adjust custom concern. Examination of action and trigger assembly revealed that the rifle was poorly maintained. Trigger would not set, and heavy build up of lubrication. Safety assembly works better than normal.*

PARTS	COMMENTS
	<i>Replaced trigger spring and clean action at 1/2 normal cost</i>
	<i>[Signature]</i>
REPAIRMAN	PROOF
GALLERY TESTER	DATE
CLEAN	TEST
TARGET	PATTE
DATE	DATE

OFFICE COPY

RD6925 REV.

BARBER - Kinzer PPS GAL RE0002348

PPS 02343