

BARBER - Kinzer PPS GAL RE0002388

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 92-24094

INITIAL JIM	CUSTOMER ORDER NO.					
DATE RECEIVED 11/06/92	DATE OPENED 11/10/92	DATE CODE	SERIAL NUMBER 6333729	NEW SERIAL NUMBER	MODEL AND GRADE 700 25-06	RDL
ACCESSORIES SCOPE BASE		L/SIGHTS		L/STUDS		
				KT 5-70 2ND TIME 1		

FROM:

HONEYCUTT, B M
RT 1 BOX 681
FLOYD

VA 24091

SHIP TO:

HONEYCUTT, B M
RT 1 BOX 681
FLOYD

VA
24091

CUST NO: 069882 C.O.D.L.

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 11-25-92	VIA UPS
IN CONDITION						REPAIR CHARGE
NEW						EXCISE
LIGHTLY WORN						TAX
WORN						INSURANCE
VERY WORN						UPS
UNREPAIRABLE						PARCEL POST
MARRED						TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
W/CLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
SLT ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
EC. ASSY.		B5		D2	E4	F4
OOD			C1	D3	E5	F5
ETAL			C2			

IN FAULT *Cannot duplicate complaint. Rifle trigger assembly does not fire normally. Trigger assembly has been tested outside factory - trigger pull is 24 pounds, this is well below our maximum spec.*

Trigger pull 24 pounds; rear lift .008"

ITS	COMMENTS <i>Offer following options:</i>					
	1) to re-adjust present trigger assembly to factory specs					
	2) to install new trigger assembly at normal cost, as getting good-will, & that will better assure confidence in the rifle.					
	REPAIRMAN DE	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92

BARBER - Kinzer PPS GAL RE0002388

PPS 02383