

BARBER - Kinzer PPS GAL RE0002406

RECEIVING AND ESTIMATING REPORT

ORDER
R 92-05273INITIAL
JJMCUSTOMER ORDER NO.
006749

STEKL

DATE RECEIVED
02/10/92DATE OPENED
02/14/92DATE CODE
AV 3-79SERIAL NUMBER
A6733138

NEW SERIAL NUMBER

MODEL AND GRADE

700 30-06

ADL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

HOPKINS, HARRY E
RR 1 BOX 349
FALLS
UPS

PA 18615

SHIP TO:

HOPKINS, HARRY E
RR 1 BOX 349
FALLS
UPSPA
18615

CUST NO: 058196 CJO.D

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

3/5/92

VIA

UPS

GUN CONDITION

- ☐ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

"The problem is that sometimes when the safety is released, it discharges."

B3

B4

B5

C1

C2

D1

D2

D3

E2

E3

E4

E5

F2

F3

F4

F5

MAIN FAULT

Cannot duplicate above complaint. Trigger and safety assembly operates normally. However, it was noted that the assembly has been adjusted improperly outside the factory. Trigger pull is poor (below our minimum specification 2) Over travel is excessive. It was also noted trigger assembly was excessively oily. See lift. 011"

PARTS

COMMENTS

Offer to clean and re-adjust present trigger assembly (if possible). Or we can offer a new trigger assembly at a normal cost as a gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 6

BARBER - Kinzer PPS GAL RE0002406

PPS 02401