

defective and would not hold cartridge number three in the magazine. The firearm was returned on December 6 for replacement of magazine.


6. On December 27 I had an opportunity to harvest a 10 Point Whitetail which would have scored in the low 150's B&C (at a minimum) but the rifle again misfired.

As detailed above, you can imagine the frustration that I have experienced with a poorly manufactured rifle, not only the hassle with the firearm but losing opportunities to harvest Trophy Whitetails in which Remington is totally at fault.

On the positive side I can assure Remington that Mark Franklin and his staff have done everything possible to rectify the situation but can not repair firearms with defective or out of specification parts from Remington.

Please advise by return mail what corrective action you and Remington Arms Company, Inc plan to initiate.

Sincerely,

  
Alvin J. Huenink

Contact Address: 806 Maple Drive  
Griffin, Georgia 30223

cc: Mark Franklin  
Franklin Sports, Inc.  
575 Hawthorne Ave.  
Athens, Georgia 30606