

CUSTOMER ORDER NO

W/1 SPENT CASE

DATE RECEIVED 12/02/85	DATE OPENED 12/09/85	DATE CODE BB 1-81	SERIAL NO. B 6282261	MODEL AND GRADE 700 30-06	BDL	ORDER 85-24
---------------------------	-------------------------	----------------------	-------------------------	------------------------------	-----	----------------

SWIVEL STUD

FROM:

SHIP TO:

SHANNON HUSTON
704 GALAXY
HARRISONVILLE, MO.

64701

PAIR CHARGE	INSURANCE	UPS	PARCEL POST	TOTAL \$
-------------	-----------	-----	-------------	-------------

GUN CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

CUSTOMER'S COMPLAINT

"Fired upon releasing safety - happened twice"

MAIN FAULT

Could not duplicate alleged malfunction - saw lower bottoming receiver and trigger assembly dripping wet with oil.

DEMERIT CODE

PARTS

Clear oil off rifle and install new style trigger assembly (no bolt. at no-charge.

Please expedite!

1/3/86

Jas.

FOR COMPUTER REF. ONLY

PROOF

(CLEAN) (TEST) (TARGET)

REPAIRMAN

OFFICE COPY

RDev.