

P.I. 2 GUN EXAMINATION REPORT NUMBER: 213 MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 09688
 OUTSIDE WORK: SIGHTS + SCOPE CORRECTIONS DATE: 3-14-81
SCOPES FROM: TECHNICAL SERVICES
 FIRED AMMO TYPE: 112T X 1104N ALBUQUERQUE, NEW
 & CONDITION: _____ GUN #: 7605936
 PROOF: (REP)B INSP.: 45 TEST: 79 CODE: B4-1-74
 HEADING: OK GA./CAL.: 24x50
 BREACH OPENING: OK CHECKED BY: JAH 4/10/80
 RECOIL SHOULDERS: OK APPROVED: JAH 4/16/80
 CHAMBER: OK APPROVED: JAH 4/16/80
 TEST: _____ APPROVED: J.B. 4-16-81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____
RIGHT MARS ON STOCK, NICK IN WOOD
AT FECTION PART
 COMPLAINT: REQUEST, PRODUCT LIABILITY EXAMINATION
 INCIDENT: _____
 COMMENTS: Sear lift .011,
- Trigger adjusting screw not factory sealed, adjuster
outside of factory. Trigger pull 2". Trigger assembly
full of gummy residue from over lubrication
causing parts to hang up.