

June 1, 1980

J. A. Stekl, Supervisor
Firearms Product Service
Remington Arms Co., Inc.
Ilion, New York 13357

RECEIVED

JUN - 5 1980

J. A. STEKL

Dear Sir:

Thank-you very much for examining my Model 700 ADL 30-06 caliber rifle, serial number A6485099. I don't agree with your analysis of the 3 incidents I reported to you (the 3rd incident was directly witnessed by 2 other people). However, I was also unable to duplicate the occurrence after flushing the trigger mechanism several times with alcohol and a spray electrical contact cleaner.

I would appreciate it if you would replace the trigger assembly as suggested in your letter of May 7. I feel that that will indeed aid in restoring my faith in the rifle. I shall await the return of the rifle. Please note that I have moved, and that my new address is given below.

Sincerely yours,

Sydney V. Jackson

Dr. Sydney V. Jackson
411 Connie
Los Alamos, N.M. 87544