

REPAIRING AND ESTIMATING REPORT

To Product Service

ORDER
R 94-01049

TIAL CUSTOMER ORDER NO.

TE RECEIVED /07/94 DATE OPENED 01/10/94 DATE CODE BN 1-93 SERIAL NUMBER C6773047 NEW SERIAL NUMBER MODEL AND GRADE 700 22-250 VS

CESSORIES W/STUDS SCOPE BASE

OM: *[Signature]*
JAMES DISCOUNT DRUGS
6TH ST
BAY SPRINGS

MS 39422

SHIP TO:
JAMES DISCOUNT DRUGS
6TH ST
BAY SPRINGS MS
39422

CUST NO: 013971 C.O.D. L

COUNT NUMBER	ACCOUNT NUMBER N/C	PROM. DATE	ESTIMATED 2-14	VIA UPS
N CONDITION		REPAIR CHARGE 25.00		
NEW		EXCISE		
LIGHTLY WORN		TAX		
WORN		INSURANCE		
VERY WORN		UPS		
UNREPAIRABLE		PARCEL POST		
MARRED		TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
W/CLE	A1	B1				
TRIGGER GROUP		B2		E1	F1	
OLT ASSY.		B3		E2	F2	
IRREL ASSY.		B4		E3	F3	
EC. ASSY.		B5		E4	F4	
OOD		C1		E5	F5	
ETAL		C2				

Will not Cook in the fire position. When safety is moved from fire position it fires in the air.

Upon receipt, rifle, inspection. Inspection revealed that all 3 trigger components have been tampered with outside the factory. Components out of specification.

RTS	COMMENTS					
	<i>Replace trigger group assembly at 1/2 normal replacement cost, in question of good work. New trigger assembly will be properly signed + sealed.</i>					
	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1/92