

Setup fee
JAY'S SPORTS ^{HC} ~~Sub Setup~~ ^{1/2} SUGGEST OR FULL PAY FOR NEW FIRE CONTROL!

FINGERPIECE OF TRIGGER HAS BEEN BADLY BENT DOWN AND REARWARD, THE END OF THE TRIGGER CONTACTS THE INSIDE OF THE TRIGGER GUARD BOW.

① DEPENDENT ON HOW TIGHT THE ACTION SCREWS ARE AND
 ② NORMAL "ROLL" OF THE ACTION IN THE STOCK, THIS GUN WILL FSR AND THEN FOLLOW DOWN.
 (NEVER FIRES ON BOLT CLOSE)

ALL SEALS REMOVED — BUT
 FIRE CONTROL SPECS OK.
 F.C. HAS BEEN REMOVED FROM ACTION, AND SAFETY FROM F.C. TOO.