

Customer Copy

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
GENERAL CONDITION: NEW R #: 24861
OUTSIDE WORK: NO DATE: 12-13-71
FROM: JENSEN BYRD Co.
FIRED AMMO TYPE: - SPOKANE, WASH.
& CONDITION: _____ GUN #: 6411367
PROOF: R.E.P.-1 ^{ASSEMBLER 90} INSP.: 55 TEST: 49 CODE: AU-3/71
HEADING: O.K. GA./CAL.: 3006
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO DAMAGED, BROKEN COMPONENTS. TRIGGER PULL SEAR-
TRIGGER CONNECTOR ENGAGEMENT AND SEAR-FIRING PIN
HEAD ENGAGEMENT WITHIN SPECIFICATIONS. TRIGGER CLEARS
TRIGGER GUARD.

COMPLAINT: FIRES WHEN BOLT IS CLOSED

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION CANNOT BE DUPLICAT-
ED. SOME FOREIGN MATERIAL IS NOTED ON THE TRIGGER
CONNECTOR WHICH MAY HAVE CAUSED IT TO STICK IN
FIRE POSITION, RESULTING IN A FOLLOW DOWN.