

DATE RECEIVED 12/21/90	DATE ORDERED 12/21/90	DATE SHIPPED 12/21/90	SERIAL NUMBER 6419763	MODEL AND GRADE 700 22-250 ADL	ORDER NO. R
---------------------------	--------------------------	--------------------------	--------------------------	-----------------------------------	----------------

ACCESSORIES SCOPE BASE

FROM: JIM MASTERS WESTERN STORES 400 GILMER ST SULPHUR SPRINGS TX 75482	SHIP TO: JIM MASTERS WESTERN STORES 400 GILMER ST SULPHUR SPRINGS TX 75482
--	---

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐ CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:	☐ NEW	☐ SLIGHTLY WORN	☒ VERY WORN	☒ MISUSED	☐ MARRED
----------------	------------------------------	--	---	---	---------------------------------

CUSTOMER'S REQUEST

"Discharges prematurely when bolt closed after loading"

MAIN FAULT: *Cannot duplicate complaint. However, trigger assembly is extremely dirty and has been improperly adjusted out of factory as evidenced by foreign sealant on adjustment screws. Trigger pull 6 pounds, insufficient over-travel, hammer non-engaged. Rifle has not been properly maintained.*

PARTS

Offer replacement trigger assembly at 1/2 normal cost, as gesture of good will.

REPAIRMAN LEW	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE