

RECEIVING AND ESTIMATING REPORT

CUST NO: 048134 C.O.D		COMMENTS ATTN D VALENT	
INITIAL JM	CUSTOMER ORDER NO.		
DATE RECEIVED 8/22/91	DATE OPENED 08/27/91	DATE CODE BL 1-91	SERIAL NUMBER C6626770
MODEL AND GRADE 700 223		ORDER R 91-16815	
ACCESSORIES W/STUDS		L/SIGHTS	

FROM:

JOHNSON, ROBERT W, III
RR 5 BOX 82
OSKALOOSA
USA

IA 52577

SHIP TO:

JOHNSON, ROBERT W, III
RR 5 BOX 82
OSKALOOSA
USA

IA 52577

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	FROM DATE	ESTIMATED 8-28	VIA UPS
--------------	--------------------	--------------------------------	------------	-----------	-------------------	------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐

NEW

☐

SLIGHTLY WORN

☐

VERY WORN

☐

MISUSED

☐

MARRED

CUSTOMER'S REQUEST

take safety off + it automatically fires

IN FAULT

As received, rifle would not cock. Disassembly revealed chipped edge on
hammer and sear-safety cam. Further examination revealed this damage was
caused from pierced primers - usually associated with overpressure.

* - As received, magazine bar was not installed up and down - but could not fit.

Sent quotation for new trigger assembly -
current assembly cannot be
repaired.

REPAIRMAN BWT	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90