

P.I. No GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 06681
OUTSIDE WORK: NO DATE: 3-15-71
FROM: KENNETH JOHNSON
FIRED AMMO TYPE: - STURTEVANT, WISC.
& CONDITION: _____ GUN #: 6312955
PROOF: R.E.P.-B INSP.: 73 TEST: 87 CODE: L.T.-2/70
HEADING: O.K. GA./CAL.: 7MM
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: EXCESSIVE RADIUS AT REAR, APPROVED: _____
BODY. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO. APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPLAINT: CLOSES HARD OVER SHELL. FIRED WHILE TRYING TO
CLOSE.

INCIDENT: CLOSE HARD

COMMENTS: THE EXCESSIVE RADIUS AT REAR OF RECOIL SHOULDER
CAUSES THE BOLT TO CAM HARD WITH A ROUND IN THE
CHAMBER. THERE APPEARS TO BE NOTHING WRONG WITH
THE TRIGGER ASSEMBLY. THE CUSTOMER LIKELY, INADVERT-
ENTLY TOUCHED THE TRIGGER WHILE TRYING TO FORCE
THE BOLT HANDLE DOWN.