

to perform a test at least ten times to be sure the firing pin remains cocked.

To me this paragraph tells me that Remington Arms knows there is a problem of some kind as a test of at least ten times should not be necessary on a quality reliable part.

I'll be waiting to hear from you very soon.

Yours Truly
Leslie Johnson

Leslie A. Johnson
RR 1 Box 309
Wheeland mo. 65779