

REMINGTON ARMS SERVICE

R-90-08295

Return as-is

F. Supry

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 28, 1990

Kawartha Arms
Attn: Mr. Ralph Bradburn
R.R. #4
Lindsay, Ont., CANADA K9V 4R4

Dear Mr. Bradburn:

Examination has been completed on the Cooley Model 600 22 rimfire rifle, serial number CG047914, that you returned to us after it was allegedly damaged while using Remington "Viper" 22 rimfire ammunition.

Our examination revealed that the mouth of the chamber was flared, and apparently had been for some time before the case ruptured and did further damage to the rifle. This is evidenced by the fact that the other fired case that was returned with the ruptured one has the same swell under the rim, resulting from no support from the flared chamber mouth. We are returning the two (2) fired cases for your inspection.

Since the damage resulted from a firearms problem rather than an ammunition problem the Remington Arms Co., Inc. cannot assume any responsibility or liability. Therefore, we are returning the rifle and two (2) fired cases to you in their present condition.

Thank you for allowing us the opportunity to examine the rifle and cases and report our findings.

Sincerely,

J.A. Stekl, Specialist
Product Service

JAS:tpv