

Cust Compl.

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: NEW R #: 027443
OUTSIDE WORK: SCOPE MOUNTED DATE: 12-22-72
FROM: KAYTON MFG. CO.
FIRED AMMO TYPE: — ALLENTOWN, PA.
& CONDITION: _____ GUN #: 6241978
ASSEMBLER C CODE: KS = 5/69
PROOF: REP-D INSP.: 74 TEST: 55 GA./CAL.: 243
HEADING: — CHECKED BY: C. PROSSER
BREECH OPENING: — APPROVED: _____
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

SEAR - TRIGGER CONNECTOR ENGAGEMENT O.K. TRIGGER
BINDING IN HOUSING. LUBRICATION LIKE GREASE ON
SEAR

COMPLAINT: FIRES WHEN SAFETY IS PUSHED OFF.

INCIDENT: FOLLOW DOWN.

COMMENTS: THE LUBRICANT USED PROBABLY CAUSED
SLUGGISH TRIGGER-CONNECTOR-SEAR RETRACTION
INTO COCKED POSITION, RESULTING IN FOLLOW DOWN.