

RECEIVING AND ESTIMATING REPORT

ORDER
R 93-00032

CUSTOMER ORDER NO.

IM

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

1/23/92

01/04/93

DS 7-69

6262897

700

22-250

ADL

ESSORIES

SCOPE BASE

L/SIGHTS

M:

KEEGAN, KENNETH
HMC 3 BOX 24
MARTIN

L

JUNT NUMBER

ACCOUNT NUMBER NYC

CONDITION

NEW

SLIGHTLY WORN

WORN

VERY WORN

INREPAIRABLE

DAMAGED

Dennis
3.75 T.P. S.L. 0045
TRIG ASSY ADJUSTED OUTSIDE
OF FACTORY ADJ. SCREWS SHOW
EVIDENCE OF BEING TAMPERED WITH
UNABLE TO DUPLICATE

Martin

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
RECEIVED	A1	B1				
TRIGGER GROUP	✓	B2			E1	F1
TRIGGER ASSY.		B3			E2	F2
REL ASSY.		B4		D1	E3	F3
TRIGGER ASSY.		B5		D2	E4	F4
TRIGGER			C1	D3	E5	F5
TRIGGER			C2			

FAULT

Stk cracked along grain by butt
Unable to duplicate customer concerns
However, observation revealed that the trigger assembly adjustment
was done by hand tampered with outside the factory.

Trigger Pull 3.75 lb.

S.L. 0045

COMMENTS Stk is repairable.

Spoke trigger assembly complete
at 1/2 normal cost. adjustment good
will

Franklin

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
FB.		✓	✓		
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

FID6925 REV. 1/92