

2-11-92

Remington Arms Co.

Ilion, NY.

ATTN/ Repair Div.

Dear Sirs -

I am returning The Remington
700 BDL 308 Win. enclosed for
inspection and repair.

IT was brought in to my shop by
a customer who stated that while unloading
the gun it fired while the bolt was
being withdrawn (at about the middle of
its length of travel) He claims his
finger was not touching the trigger
when it happened.

I am requesting that the gun and
in particular the trigger be examined for
defects and any repairs be made.
that are necessary.

Please furnish as soon as possible
what you believe to be the problem and
what will be done to correct it.

I have enclosed a F.F.L. copy
and card for your files.

Cordially, *B. J. Kersch*

Brace Kerschmer
205 Jefferson St.
Sch. Haven Pa 17972

Schoy/Kill