

BARBER - Kinzer PPS GAL RE0002747

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-01326

INITIAL

CUSTOMER ORDER NO.

W/I SPENT CASE

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

01/10/94

01/11/94

FN 6-93

C6806608

700 30-06

ADL

ACCESSORIES

W/STUDS

XC F. Supra

FROM:

SHIP TO:

KIRBY RD GUN SHOP
770 S KIRBY RD
BLOOMINGTON

KIRBY RD GUN SHOP
770 S KIRBY RD
BLOOMINGTON

IN 47403

IN
47403

CUST NO: 043309 C.B.D.

ACCOUNT NUMBER

ACCOUNT NUMBER NC

063103

WRITE

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW

☐ LIGHTLY WORN

☐ WORN

☐ VERY WORN

☒ UNREPAIRABLE

☐ MARRED

** 1/2 Retail*

Hold for reply

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Customer took gun home, fired it and the wood splintered and the trigger housing came out

MAIN FAULT

Mfg date 6/93 Gun was subjected to extreme high pressure. Band had to be unscrewed in order to remove breech bolt from Receiver. Examination of the incident casing confirms excessive pressure showing 'near' head separation. The incident shell did not have a factory crimp on the neck. Origin/mfg of shell is not Remington Factory produced. However, as a strictly as a gesture of good will offer replacement rifle at

PARTS

COMMENTS

Remo #

1/2 price

Retain incident shell until resolved.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/92