

RECEIVING AND ESTIMATING REPORT

CUST NO: 049706 C.O.D

COMMENTS

DATE RECEIVED 9/19/91	CUSTOMER ORDER NO. JM 006435	DATE OPENED 09/24/91	DATE CODE CH 4-87	SERIAL NUMBER B6859253	MODEL AND GRADE 700 280	MTN	ORDER R 91-18831
--------------------------	---------------------------------	-------------------------	----------------------	---------------------------	----------------------------	-----	---------------------

ACCESSORIES W/STUDS SCOPE BASE

FROM:

KIRK, JAMES
BOX 168 RTE 70A
TABERG
USA

NY 13471

SHIP TO:

KIRK, JAMES
BOX 168 RTE 70A
TABERG
USA

NY 13471

COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 10-4-91	VIA DOOR
--------------	--------------------	--------------------------------	------------	------------	----------------------	-------------

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Gun fired when safety was placed in fire position without pulling trigger

MAIN FAULT

Trigger assembly rusted from unknown source (also rust on bottom side of barrel). Internal trigger parts not moving properly. rust duplicate complaint at this time, however, rust on trigger pivot pin could have caused problem.

ARTS	REPAIRMAN DE	PROOF	CLEAN	TEST	TARGET	PATTERN
	GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90