

*Carl Chrysler*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700  
GENERAL CONDITION: NEW R #: 019718  
OUTSIDE WORK: NO DATE: 10-5-72  
FROM: K MART ENTERPRISE,  
ROYAL OAK, MICH.  
FIRED AMMO TYPE: - GUN #: 6258285  
& CONDITION: \_\_\_\_\_ CODE: 05 = 7/69  
PROOF: R.E.P. - A ASSEMBLER 90 INSP.: 58 TEST: 49 GA./CAL.: 3006  
HEADING: O.K. CHECKED BY: C. PROSSER  
BREECH OPENING: - APPROVED: \_\_\_\_\_  
RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
CHAMBER: O.K. APPROVED: \_\_\_\_\_  
TEST: NO APPROVED: \_\_\_\_\_  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_

SEAR - CONNECTOR ENGAGEMENT .010 (MIN. IS .020)SOLIDIFIED LUBRICANT ON SIDE OF SEAR.COMPLAINT: "FIRES WHEN EJECTING SHELLS."INCIDENT: FOLLOW DOWN

COMMENTS: THE SOLIDIFIED LUBRICANT CAUSED THE SEAR  
TO STAY DOWN IN FIRED POSITION. WHEN THE BOLT  
WAS ROTATED TO LOCK-UP, FOLLOW DOWN OCCURRED.