

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO. D916767		COMMENTS			
DATE RECEIVED 12/06/90	DATE OPENED 12/12/90	DATE CODE PD 6-83	SERIAL NUMBER B646804B	MODEL AND GRADE 700 30-06 ADL		ORDER R 90-3240	
ACCESSORIES W/STUDS							

FROM:

K MART ENTERPRISES

P.O. BOX 3150
TROY MI 48084

SHIP TO:

K MART 4166-B0
5956 CENTRAL AVE W

TOLEDO

OH

43616

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 1-2-91	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	---------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

Gun fires when safety is taken off

MAIN FAULT

No fault found - trigger and safety assembly operates normally - Trigger pull 4#; cam - lift .072" - cannot duplicate complaint. However, trigger assembly is contaminated with staining residue (Bolt stop is sticking to receiver not moving freely). The sticky area coupled with cold temperatures could cause problems.

PARTS

Send quote to clean present trigger assembly (if possible) or, we can install a new trigger assembly at normal cost as a gesture of good-will if it will further restore confidence in the rifle.

REPAIRMAN RBS	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90