

M/600 Custom Comp. Rifle

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 600
GENERAL CONDITION: NEW R #: 013900
OUTSIDE WORK: SWIVELS ADDED DATE: 7-6-72
FROM: AL KNABB
FIRED AMMO TYPE: - FLEETWOOD, PA.
& CONDITION: _____ GUN #: 96981
PROOF: R.E.P. ASSEMBLER # 18 INSP.: U TEST: _____ CODE: EP = 10/67
HEADING: - GR./CAL.: 6MM REM.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

CONNECTOR-SEAR ENGAGEMENT, 0.10, MIN. IS .020. TRIG-
GER PULL 4 POUNDS. FRONT TRIGGER ADJUSTING SCREW
BACKED OUT SO THAT TRIGGER RETRACTION IS NOT POSITIVE.
TRIGGER RUBBING LEFT SIDE OF HOUSING.

COMPLAINT: "SHELL FIRED WHEN I TOOK THE RIFLE OFF SAFETY."

INCIDENT: FOLLOW DOWN

COMMENTS: THE COMBINATION OF UNDER MIN. CONNECTOR-SEAR
ENGAGEMENT, ERRATIC RETRACTION AND SLIGHT TRIGGER
BIND, RESULT IN FOLLOW DOWN.