

Chamber Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700
GENERAL CONDITION: NEW R #: 27774
OUTSIDE WORK: NO DATE: 12-10-70
FROM: KROEGERS FARM
SUPPLY
DURANGO, COLO.
FIRED AMMO TYPE: - GUN #: 6367225
& CONDITION: ASSEMBLER V CODE: DT-9/70
PROOF: R.E.P.A INSP.: 58 TEST: 13 GA./CAL.: 3006
HEADING: - CHECKED BY: C. PROSSER
BREECH OPENING: - APPROVED: _____
RECOIL SHOULDERS: - APPROVED: _____
CHAMBER: - APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

COMPONENTS O.K.COMPLAINT: "HAMMER IN BOLT WILL NOT STAY COCKED."INCIDENT: FOLLOWS DOWN.

COMMENTS: SEAR, TRIGGER CONNECTOR, ENGAGEMENT
ADJUSTED TOO CLOSE (.005) MINIMUM IS .015, THIS
LETS THE SEAR SLID OFF THE CONNECTOR UNDER
PRESSURE & FIRING PIN FOLLOWS DOWN.
RE-ADJUSTED ENGAGEMENT.