

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS			
IJM							
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE		ORDER	
11/09/91	01/15/91	LI 2-76	A6264948	700	308	ADL	R 91-01460
ACCESSORIES		SCOPE BASE					
W/STUDS		L/REAR SIGHT					

FROM:

KUKELKORNS GUN SHOP
795 CAROLINA AVE
ORANGEBURG

SC 29115

SHIP TO:

KUKELKORNS GUN SHOP
795 CAROLINA AVE
ORANGEBURG

SC 29115

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
						UPS

EXCHANGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL

GUN CONDITION:

☐ NEW☐ SLIGHTLY WORN☐ VERY WORN☐ MISUSED☐ MARRED

CUSTOMER'S REQUEST

"as my customer says it has gone off three times when the safety was taken off."

MAIN FAULT

Trigger assembly has been improperly adjusted outside of factory - sealant missing from all adjustment screws - external over-travel, insufficient rear engagement - assembly not operating properly. Closing bolt foot causing firing pin to follow down.

PARTS

Send your quotation for new trigger assembly at normal cost, as gesture of good-will.

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
REW					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6923 REV. 7/90