

660

Customer Complaint

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 660
GENERAL CONDITION: NEW R #: 011064
OUTSIDE WORK: SCOPE MOUNTED DATE: 5-17-72
FROM: LAKEVIEW SPT. SHOP
FIRED AMMO TYPE: - SANDY LAKE, PENNA.
& CONDITION: _____ GUN #: 106009
PROOF: R.E.P INSP.: U TEST: 87 CODE: LR = 2/68
HEADING: O.K. GA./CAL.: 243 WIN.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: NO APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

NO BROKEN COMPONENTS. SLIGHT ROUNDING AT EDGE OF
CONNECTOR. BURR ON CORNER OF SEAR. GREASE TYPE
OF LUBRICATION INSIDE HOUSING & ON SIDES OF TRIGGER.
SEAR - CONNECTOR ENGAGEMENT .015 TRIGGER PULL
4 POUNDS.

COMPLAINT: "WHEN THE SAFETY IS RELEASED, IT FIRES."

INCIDENT: FOLLOW DOWN

COMMENTS: THE CUSTOMER'S MALFUNCTION WAS NOT DUPLICATED.
THE BURR ON THE SEAR COMBINED WITH TOO HEAVY
LUBRICANT PROBABLY BROUGHT ABOUT FAILURE OF
CONNECTOR-TRIGGER TO RETRACT AND FOLLOW DOWN.