

RECEIVING AND ESTIMATING REPORT

ER ORDER NO.		COMMENTS POTTER	
RECEIVED 30/87	DATE OPENED 07/01/87	DATE CODE PU 6-71	SERIAL NUMBER 6448126
MODEL AND GRADE 700 30-06		ORDER R 87-13298	
DRIES W/STUDS		BDL	

SHIP TO: MARV LANGOHR 8909 HWY. 57 BAILEYS HARBOR, WI. 54202		SHIP TO: 9/22/87 Disposition Return Gun N/C to customer RHP	
ITEM NUMBER	PROM. DATE	ESTIMATED	VIA
		7/22	UPS
TARGE	TAX ST	INSURANCE	UPS
	TAX CITY	PARCEL POST	TOTAL \$

CONDITION: ☐ NEW ☒ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ QUOTE

OWNER'S COMPLAINT:
 2 yr time back for misfires in cold weather —
 see 2 misfires which show very light FP blow
 SEE customer letter
 failed the null ~~test~~ & screwdriver test.
 Lubricated oil in firing pin assembly

fit trigger assem

no change

2W Field

DP 56 US

DEMERT CODE

Disposit 7-21-87 RHP Potter

① Clear up firing pin / + spring —
 replace if necessary.

② Make sure FP pin is not
 binding in bolt body. If
 lub'c required, use dry
 graphite.

③ When repair completed + gun
 shot: call Roger Potter. Don't ship.

PROOF
 ✓✓ Word done

REPAIRMAN
 L.S.

COMPUTER REF. ONLY

OFFICE COPY

RD4925 REV. 3/86