

ORDER
R 92-10642

FROM: LARRYS SPORT CTR
60 OREGON CITY SHPG CTR
OREGON CITY OR 97045

SHIP TO: LARRYS SPORT CTR
60 OREGON CITY SHPG CTR
OREGON CITY OR 97045

CUST NO:007825 WILM

GUN CONDITION		REPAIR CHARGE	
☐ NEW		EXCISE	
☐ LIGHTLY WORN		TAX	
☐ WORN		INSURANCE	
☐ VERY WORN		UPS	
☐ UNREPAIRABLE		PARCEL POST	
☐ MARRED		TOTAL	

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.	<i>"Close bolt, firing pin fires almost all the time."</i>					
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

As received, trigger assembly inoperative. Trigger assembly contaminated with gunning substance - near safety cam - stuck & not plating trigger housing.
Improper maintenance.

[illegible]

OFFICE COPY

RD6925 REV. 1

BARBER - Kinzer PPS GAL RE0002911

PPS 02906