

*Customer Copy*

P.I. NO GUN EXAMINATION REPORT NUMBER: \_\_\_\_\_ MODEL: 700  
GENERAL CONDITION: NEW R #: 29996  
OUTSIDE WORK: FRONT TRIGGER ADJUSTING DATE: 1-4-71  
SCREWS RE-ADJUSTED. FROM: LEFAVOR'S SKI SHOP  
FIRED AMMO TYPE: - WILMINGTON, MASS.  
& CONDITION: \_\_\_\_\_ GUN #: 6369151  
ASSEMBLER 13  
PROOF: R.E.P.-E INSP.: 0 TEST: 98 CODE: DT-9/70  
HEADING: O.K. GA./CAL.: 3006  
BREECH OPENING: - CHECKED BY: C. PROSSER  
RECOIL SHOULDERS: O.K. APPROVED: \_\_\_\_\_  
CHAMBER: O.K. APPROVED: \_\_\_\_\_  
TEST: NO. APPROVED: \_\_\_\_\_  
COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: \_\_\_\_\_  
NO DAMAGED OR BROKEN PARTS.

COMPLAINT: "SEVERAL TIMES GUN WENT OFF WHEN CLOSING BOLT."

INCIDENT: FOLLOWS DOWN

COMMENTS: SEAR-TRIGGER CONNECTOR ENGAGEMENT .005,  
MINIMUM IS .015. THIS LETS THE SEAR SLIP OFF THE  
CONNECTOR UNDER PRESSURE AND FOLLON DOWN  
RESULTS.