

RECEIVING AND ESTIMATING REPORT ✓

INITIAL JJM		CUSTOMER ORDER NO. 5529		COMMENTS					
DATE RECEIVED 01/09/91	DATE OPENED 01/15/91	DATE CODE BI 1-88	SERIAL NUMBER C6217064	MODEL AND GRADE 700 30-06 ADL			ORDER R 91-013		
ACCESSORIES W/STUDS									

FROM:

LEWIS ARMS
1575 HOOKSETT
HOOKSETT,

NH 03106

SHIP TO:

LEWIS ARMS
1575 HOOKSETT
HOOKSETT,

NH
03106

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	-----------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

GUN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

CUSTOMER'S REQUEST

Problem with safety

MAIN FAULT

*Trigger assembly rusted from unknown source - internal
trigger parts not moving freely nor properly*

PARTS

*Repair trigger assembly at 700 -
charge, as gesture of good-will*

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90