

RECEIVING AND ESTIMATING REPORT

CUST NO: 006944 TLIDN		COMMENTS		220	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
8/28/91	09/03/91	DU 9-71	6481228	700 7MMAG BDL	R 91-17220
ACCESSORIES		W/STUDS		SCOPE BASE	

FROM:	SHIP TO:
LEXINGTON HDWE CO. 23 SOUTH MAIN ST. LEXINGTON USA	LEXINGTON HDWE CO. 23 SOUTH MAIN ST. LEXINGTON USA
VA 24450	VA 24450

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA
					9/12/91	UPS

PAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
-------------	-----	-----------	-----	-------------	-------

UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED

STOMER'S REQUEST "This rifle fired at times when shooting but also at times when taking off safety, and not "touching" trigger."

IN FAULT Cannot duplicate above complaints. However, removal of action from rifle revealed that the interior of the action is extremely dirty and dirty; also, the trigger assembly is contaminated with excessive lubrication, both wet and dried. Rifle has not been properly maintained. Trigger pull 5 pounds; also - left .009"

- 1) Clean entire rifle
- 2) Clean trigger assembly, if possible; if not, quote new assembly at the price as gesture of good-will

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
RTS					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 7/90