

10-3-79 RECEIVED
 10-10-79
 008 L.F.T.
 trigger pull 1 1/4 lbs.

BUILDING 30
 DENVER TECHNOLOGICAL CTR.
 8301 EAST PRENTICE AVE.
 ENGLEWOOD, COLO. 80110

TALL
 MS INC.
 E.
 NN.

06602

MODEL: 700 A

R #: 25733

DATE: 10-3-79

FROM: LIBERTY MUT.
 BUILDING 3

8301 E. PRENTICE
 ENGLEWOOD CO

GUN #: 6853510

CODE: CZ = 4-75

GA./CAL.: 2506

CHECKED BY: M-HARDY

APPROVED: JPM 10/19/79

APPROVED: RJA 10/12/79

APPROVED: R.B. 10-18

APPROVED: JPM 10-18

WAB 10-18

RECOIL

CHAMBER

TEST:

COMPONENT

Old Style)

SA

IN STD = 4

B. SET M U Z Z L E - barrel is added in stock
 outside of plant. Barrel pad removed

COMPLAINT: GUN WENT OFF WHEN CHAMBERING
 LIVE ROUND

INCIDENT: HOLE IN ROOF OF PICK UP TRUCK
 CONCUSSION BASTE EAR DRUM

COMMENTS: Trigger assembly adjusted outside factory. Sealant
 missing on 3 screws. Trigger adjusting screw has been
 backed out reducing trigger pull. Trigger pull 1 1/4 #
 Remington spec 3# to 5#. No return spring force on trigger.