

P.I. YES GUN EXAMINATION REPORT NUMBER: 155 MODEL: 700 A
 GENERAL CONDITION: FAIR R #: 25733
 OUTSIDE WORK: SCOPE BASE ADDED DATE: 10-3-79
 FROM: LIBERTY MUTU
BUILDING 30
 FIRED AMMO TYPE: NOT KNOWN 8301 E. PRENTICE
ENGINE 4000 E.
 & CONDITION: GUN #: 6853510
 PROOF: REP/IF INSP.: 62 TEST: 97 CODE: CZ = 4-75
 HEADING: OK GA./CAL.: 2506
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: JAH 10/19/79
 CHAMBER: OK APPROVED: REP 10/12/79
 TEST: APPROVED: R.B. 10-18-79
 APPROVED: JAH 10-18-79
 APPROVED: WJH 10-18-79
 COMPONENT CONDITION: (Damaged, Broken, Old Style)
SMALL DENTS IN STOCK
BRIGHT Muzzle - Barrel reloaded in stock
outside of plant. Barrel had removed

COMPLAINT: GUN WENT OFF WHEN CHAMBERING
LIVE ROUND

INCIDENT: HOLE IN ROOF OF PICK UP TRUCK
CONCUSSION BATE EAR DRUM

COMMENTS: Trigger assembly adjusted outside factory. Sealant
missing on 3 screws. Trigger adjusting screw has been
backed out reducing trigger pull. Trigger pull 1 1/4 #
Remington spec 3# to 5#. No return spring force on trigger