

October 15, 1992

Mr. Stekl  
Remington Fire Arms  
14 Hoefler Ave.  
Ilion, NY 13357

Mr. Stekl:

Enclosed please find the Remington Model 700 BDL 30-06 rifle, S/N A6478653, we discussed today.

This rifle seriously malfunctioned during my recent elk hunting trip. I had returned to our base camp and went to unload the rifle. When I turned off the safety it immediately fired.

A friend of mine had a 7mm model 700 BDL that discharged under the same circumstances. He has since sold his Remington and purchased a different rifle.

I know of only one other owner of the model 700 BDL and both of our rifles have demonstrated this defect.

As I mentioned, if the repairs and/or updates are going to exceed the \$15.00 please return the rifle to me unrepai red and I will sell it and purchase a more reliable rifle.

Best Regards.

Rob Liepse  
133 East 5th Ave.  
Longmont, Colorado 80501  
(303)772-4561 Home  
(303)451-1300 Work (daytime)