

P.I. NO GUN EXAMINATION REPORT NUMBER: 467 MODEL: 700 ADL
 GENERAL CONDITION: POOR - DIRTY R #: 16802
 OUTSIDE WORK: RECOIL PAD & STUDS ADDED DATE: 6-12-81
SCOPE SCREWS REMOVED FROM: LOUISIANA WITNESS
SCOPE SCREWS REMOVED FROM: SUPPLY INC.
 FIRED AMMO TYPE: NOT KNOWN P.O. BOX 2961, 402 H. RODERIG
 ST. MORGAN CITY, LA.
 & CONDITION: _____ GUN #: 635514/1
 PROOF: A INSP.: 9 TEST: 87 CODE: OT: 7-70
 HEADING: OK GA./CAL.: 3006
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SECULDERS: OK APPROVED: G.M. 6/24/81
 CHAMBER: OK APPROVED: PER 6/22/81
 TEST: _____ APPROVED: F.M. 6/22/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: AS 6/22/81
- BRIGH METAL + RUST ON BBL.
BOLT RUSTY POOR FIT OF RECOIL PAD
 COMPLAINT: SAFETY WONT WORK + TRIGGER GOES OFF
WITH OUT PULLING WHEN WORKING BOLT
 INCIDENT: _____
 COMMENTS: Fire control gummed up. Sean safety cam sticks
in down position. Excessive gunk in fire control.
Replace fire control - charge customer.
- Trigger pull 3#
- gun passes tick test.