

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 ADL
 GENERAL CONDITION: NEW R #: 07070
 OUTSIDE WORK: TRIGGER ENGAGEMENT SCREW DATE: 4-23-71
SEAL REMOVED. FROM: LLOYD Co.
 FIRED AMMO TYPE: - LITTLE ROCK, ARK.
 & CONDITION: _____ GUN #: 6266361
ASSEMBLER G5
 PROOF: R.E.P.-E INSP.: 73 TEST: 87 CODE: WS = 8/69
 HEADING: O.K. GA./CAL.: 22-250
 BREECH OPENING: - CHECKED BY: C. PROSSER
 RECOIL SHOULDERS: O.K. APPROVED: _____
 CHAMBER: O.K. APPROVED: _____
 TEST: NO APPROVED: _____
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: _____

TRIGGER CONNECTOR BROKEN. TRIGGER SPRING MISSING.
TRIGGER ENGAGEMENT SCREW OUT OF ADJUSTMENT.

COMPLAINT: "LEVER IN TRIGGER HOUSING BROKEN"

INCIDENT: -

COMMENTS: APPARENTLY A DEFECTIVE TRIGGER CONNECTOR WAS
USED.