

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER

R 93-26496

CUSTOMER ORDER NO.

S

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

ADL

/30/93

12/09/93

AY 3-74

6724393

700 30-06

ACCESSORIES

W/STUDS

DM:

Full Super
 LOVE, JERRY
 1321 9TH WEST
 KEMMERER

WY 83101

SHIP TO:

LOVE, JERRY
 1321 9TH WEST
 KEMMERER

WY
 83101

CUST NO: 088284 C.B.D

QUANTITY

ACCOUNT NUMBER N/C

WRITE ☐

FROM DATE

ESTIMATED

VIA

UPS

CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

MARRED

REPAIR CHARGE

25.00

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CLE

A1

B1

GGER GROUP

B2

E1

F1

LT ASSY.

B3

RREL ASSY.

B4

D1

E3

F3

C. ASSY.

B5

D2

E4

F4

MOD

C1

D3

E5

F5

TAL

C2

FAULT

*Upon receipt, unable to duplicate Customer Concern.
 Examination reveals that the action and trigger assembly are covered
 with dirt, wax, and a heavy sticky substance. Best step would
 be to clean and replace trigger assembly. Mfg 1974*

COMMENTS

*Replace compact trigger
 assembly and clean action set
 1/2 normal replacement cost*

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE