

Please find this rifle for reply.
Thank you,
Jim

RRR-103

W.F. Miller
F.T. Miller
R.D. Green
R.J. Sperling
D.J. Smith
2-00065

Fit Now Trigger
OK. Pul Jim Prall
2/10/82

January 20, 1982

Regis Kart 425
Miss. Hwy. 80
Grenada, Mississippi 38901

Gentlemen:

Examination has been completed on your customer's Model 700 RFL 30-06 caliber rifle, serial number A4414389, which you returned to us because "the gun will go off even when the safety is on".

The returned firearm, which was produced in February of 1977, has been examined by our firearms experts who report that it contained our high-pressure proof test, gallery test, and final inspection stampings, indicating that it had successfully passed all our necessary tests prior to shipment.

The general condition of the gun appeared to be fair, and it was noted that the stock contained slight nicks and the color was worn off the barrel muzzle. In going over the individual parts, we found the headspace, recoil shoulders, and chamber all to be normal.

Examination of the rifle and trigger assembly could not duplicate the malfunction that was reported. All parts tolerances and dimensions were found to be normal, including sear-connector engagement. Also, factory seals were intact on the trigger adjustment screws, indicating no alterations were made on the trigger outside our company. Trigger pull was well within our specifications at 4 pounds.

Based on our findings, Remington Arms Company, Inc., cannot accept any liability or responsibility for the alleged incidents. We can only assume that accidental contact was made with the trigger, with the safety in the "fire" position, causing the rifle to fire; since by design when the safety of a Model 700 rifle is in the "safe" position the firing pin is blocked, and it is not mechanically possible for it to fall unless the safety is moved to the "fire" position and the trigger pulled.

-1-

Paul Kirk

SHIPPING CHECK