

RECEIVING AND ESTIMATING REPORT ORDER
R 94-15613

INITIAL: _____ CUSTOMER ORDER NO.: _____

FDC

DATE RECEIVED 05/04/94	DATE OPENED 05/05/94	DATE CODE BI 1/88	SERIAL NUMBER A6253284	NEW SERIAL NUMBER	MODEL AND GRADE 700 220250	REM. VARM.
ACCESSORIES W/STUDS SCOPE BASE SWIVEL						

FROM: MAJOR TRUE VALUE
JACKSON ST.
HOPE IN 47240

SHIP TO: MAJOR TRUE VALUE
JACKSON ST.
HOPE IN 47240

CUST NO. 996940 C.O.D.

ACCOUNT NUMBER	ACCOUNT NUMBER NC	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	-------------------	--------------------------------	------------	-----------	------------

GUN CONDITION

☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE \$200.00
 EXCISE
 TAX
 INSURANCE
 UPS
 PARCEL POST
 TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT: Upon receipt, we could not duplicate the customer concern.
 With diff. 1988 Remington model that the action and trigger assembly are found with a
 heavy gunny body, action. Shot on steel and copper. Both sets were not
 about

PARTS: #26345 Trigger Assembly

COMMENTS: Trigger will manual 5 to 6 lbs
 and released, some left with 5 lbs

Before complete trigger assembly was
 done action at the manual operation and
 at trigger of good use.

to deliver

REPAIRMAN TAL	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY RD925 REV. 1/94