

not let accumulate in or on the trigger assembly, as both of these conditions could adversely affect the operation of the trigger assembly.

Since we found your customer's rifle to function properly in every respect, we are prepared to have it returned, however, as a gesture of good will, and to restore confidence in the rifle, we are replacing* the complete trigger assembly at no charge. Please allow two (2) weeks to have this service performed.

Thank you for affording us the opportunity to examine the rifle and report our findings, and trust our action meets with your approval.

Sincerely,



D.J. Sanita
Product Service

DJS:tpp

Remington Arms Company, Inc.