

RECEIVING AND ESTIMATING REPORT

INITIAL JJM		CUSTOMER ORDER NO.		COMMENTS			
DATE RECEIVED 12/21/90	DATE OPENED 01/02/91	DATE CODE CU 4-71	SERIAL NUMBER 6419703	MODEL AND GRADE 700 22-250 ADL		ORDER R 91-000	
ACCESSORIES SCOPE BASE							

FROM:

JIM MASTERS WESTERN STORES
400 GILMER ST
SULPHUR SPRINGS TX 75482

SHIP TO:

JIM MASTERS WESTERN STORES
400 GILMER ST
SULPHUR SPRINGS TX
75482

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

REPAIR CHARGE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

GUN CONDITION:

☐

NEW

☐

SLIGHTLY WORN

☒

VERY WORN

☐

MISUSED

☐

MARRED

CUSTOMER'S REQUEST

"Discharges prematurely when fast closed after loading"

MAIN FAULT

Cannot duplicate complaint. However, trigger assembly is extremely dirty and has been improperly adjusted out of factory as evidenced by foreign sealant on adjustment screws. Trigger pull 6 pounds, insufficient over-travel, excessive rear engagement. Rifle has not been properly maintained.

PARTS

Offer replacement trigger assembly at 1/2 normal cost, as gesture of good-will.

REPAIRMAN

LEW

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

STOK/

RD6925 REV. 7