

RECEIVING AND ESTIMATING REPORT

TIAL		CUSTOMER ORDER NO.		COMMENTS			
PS							
TE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER		
5/10/91	05/13/91	PI 6-B8	A6310434	700 243 WIN ADL	R 91-10741		
ACCESSORIES		W/STUDS					
FROM:		L/REAR SIGHT				SHIP TO:	
THE MATTHEWS GROUP 709 COUNTRY LANE HOUSTON TX 77024		THE MATTHEWS GROUP 709 COUNTRY LANE HOUSTON TX 77024					
COUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS	
PAIR CHARGE TAX INSURANCE UPS PARCEL POST TOTAL UN CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED STOMER'S REQUEST <i>Fines when bolt is closed. - on chamber of rd</i> IN FAULT <i>Cannot duplicate complaint - many attempts were made to duplicate with dummy round in chamber - firing pin did not fall. Trigger assembly is contaminated with sticky residue. However, rear-safety even grooves slowly in recovery. Trigger pull 5 pounds, rear-lift .209". Rifle could not be made to malfunction.</i> RTS <i>Offer to clean present trigger assembly, if possible, or, we can install a new trigger assembly at ± normal cost, as a gesture of good-will if it will better restore confidence in the rifle.</i>							
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN		
<i>HB</i>							
BARBER TESTER	DATE	DATE	DATE	DATE	DATE		

OFFICE COPY

RD6925 REV. 7/90