

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

May 2, 1985

Mr. Richard M. Maupin
12198 Dorset Dr.
Cincinnati, Ohio 45242

Dear Mr. Maupin:

We are in receipt of your Model 700 ADL center fire rifle in 22-250 Rem. caliber, serial number B6428213, which was sent to us by Cincinnati Gun Headquarters for a trigger problem.

Our experts have fully examined the bolt and fire control assemblies and conclude both parts meet all Remington quality criterion. Every aspect of the trigger assembly is entirely within specification including the safety which fully engages. Our determination was made after a series of experts carefully examined the firearm and repeatedly attempted to fire the assembly under various stress conditions. The only way the trigger could be made to fire was to pull the trigger with the safety in the fire position.

Since we find nothing wrong with the trigger, we will return it to you as received if you so choose. However, if you prefer we install a new trigger assembly, we will promptly do so on a no charge basis. Please notify us of your decision, by mail, and we will proceed accordingly.

We await your reply, Mr. Maupin, and wish you every hunting and shooting success.

Sincerely,

R.H. Potter, Supervisor
Product Service

RHP:tpg