

RECEIVING AND ESTIMATING REPORT

COMMENTS

CROSSLIN, ROBERT

ORDER

R 91-26657

CUSTOMER ORDER NO.

RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

16/91

12/19/91

PA 6-80

B6219668

700 7MMAG

BDL

ACCESSORIES

W/STUDS

SCOPE BASE

L/REAR SIGHT

M:

SHIP TO:

MAYFIELD GUN SHOP
ROUTE #4 BOX 33
MAYFIELD
USA

KY 42066

MAYFIELD GUN SHOP
ROUTE #4 BOX 33
MAYFIELD
USAKY
42066

CUST NO:001942 ILION L

COUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

FROM DATE

ESTIMATED

VIA

UPS

CONDITION

NEW

LIGHTLY WORN

WORN

VERY WORN

UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CLE	A1	B1				
GGER GROUP		B2			E1	F1
LT ASSY.		B3			E2	F2
RREL ASSY.		B4		D1	E3	F3
C. ASSY.		B5		D2	E4	F4
OD			C1	D3	E5	F5
TAL			C2			

N FAULT

Trigger assembly is contaminated with gumming, sticky substance
 as received, rear-safety cam was sticking to side plate of trigger
 assembly - internal trigger parts not moving or rotating properly
 cause of sticky condition.

Trigger pull - 4 1/2 pounds; Rear-lift .012"

ITS

COMMENTS

Clean present trigger assembly,
 if possible; if not, offer replacement
 trigger assembly at normal cost,
 as a gesture of good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE